







1. *For information only.
2. Non mentioned tolerances-holes H16, shafts h16, other $\pm IT16/2$.
3. Not mentioned surface roughness Ra 12,5.
4. Before welding pos. 5 and pos. 6 shell seam must be grinded.
5. Cylinder's diameter must be check acc. top end and buttom end.
6. PT 100% control for all covered seams of cylinder pos.2.
7. Customer tag No must be stamped on outer surface of det. pos. 5.
8. Dimmensions: at 0°-194*; at 90° and 270°- 289*; at 180°-383* mm.

[illegible]